

CARDONE ProTech

Supporting Today's Professional Technician



Determining the Correct Window Lift for Certain Fords

Application:

Ford, Ford truck, Mercury, Mercury truck, and Lincoln vehicles equipped with power windows.

Problem:


CARDONE unit does not match the original.

Cause:

The original equipment manufacturer interchanged motors to suit their production needs. The result is that the opposite side part number is actually needed.

Solution:


First verify that the unit in the box is correct (refer to sample pictures below and on reverse side). If correct, order opposite side.




42-31, 42-313, 42-315



42-32, 42-312, 42-314




42-305




42-304


For other ProTech publications, visit www.cardone.com
CARDONE Industries, Inc. • 5501 Whitaker Ave. • Philadelphia, PA 19124-1799




42-307




42-306




42-339




42-338




42-351



42-350



42-389



42-388