

CARDONE ProTech



Supporting Today's Professional Technician



GM PASSLOCK Relearn Procedure

Application:

All OBD-II (1996 and newer) GM vehicles equipped with the PASSLOCK anti-theft system.

Problem:

Vehicle will not start after the original ECM has been replaced.

Cause:

The original ECM has a security code (PASSLOCK) stored in its memory that matches the vehicle's instrument panel cluster or security module (if so equipped). The replacement ECM can only receive the PASSLOCK code after it is installed in the vehicle and a relearn performed on the ECM.

Solution:

Because the procedure is vehicle specific, it will be necessary to reference the vehicle service manual (or sources such as All Data or Mitchell-on-Demand) for the correct procedure.



For other ProTech publications, visit www.cardone.com
CARDONE Industries, Inc. • 5501 Whitaker Ave. • Philadelphia, PA 19124-1799