

# CARDONE ProTech

Supporting Today's Professional Technician



## In-Line Power Steering Filter — An Ounce of Prevention

**Application:**

All power steering equipped vehicles.

**Problem:**

Premature failure of power steering components.

**Cause:**

Particles not removed during the flushing process or particles from everyday wear of components and hoses cause valves to stick and block fluid flow.

**Solution:**

When replacing any power steering component, always flush the entire system and then install an in-line filter such shown below (part 20-0038F). Be sure to use OE recommended or equivalent fluid, see Pro Tech 20-0027 for more information.



In-Line Filter 20-0038F

**Note:**

This ProTech bulletin is supplied as technical information only and is not an authorization for repair.

For other ProTech publications, visit [www.cardone.com](http://www.cardone.com)  
CARDONE Industries, Inc. • 5501 Whitaker Ave. • Philadelphia, PA 19124-1799