

# CARDONE ProTech

Supporting Today's Professional Technician



## Don't Let the Power Steering Snake Bite You

**Application:** All vehicles equipped with power steering.

**Problem:** Power steering component failure ( i.e., Rack & Pinion, Gear Box, Pump, Control Valve or Power Cylinder).

**Cause:** Contamination in the steering system.

**Solution:** During installation of the replacement unit carefully inspect the hydraulic hoses. Hoses that appear harmless may have hidden problems. They deteriorate from the inside out, passing contamination throughout the entire system. This results in premature failure of the steering system. ALWAYS FLUSH THE ENTIRE SYSTEM AND REPLACE HOSES TO PREVENT WARRANTY PROBLEMS.



**FAILURE TO REPLACE  
HOSES COULD COME  
BACK TO BITE YOU!**

For other ProTech publications, visit [www.cardone.com](http://www.cardone.com)  
CARDONE Industries, Inc. • 5501 Whitaker Ave. • Philadelphia, PA 19124-1799