


CARDONE ProTech

Supporting Today's Professional Technician



CRUISE CONTROL TRANSDUCER TROUBLESHOOTING—GM 1969-84

The chart below can be used to trouble-shoot most Cruise Control Transducers. Refer to your vehicles' service manual for specific diagnostic procedures and adjustments.



Note:

Each ¼ turn will change vehicle speed one mph. Accuracy testing should be done at 55 mph. Refer to vehicles' service manual for specific adjustment.

For other ProTech publications, visit www.cardone.com
CARDONE Industries, Inc. • 5501 Whitaker Ave. • Philadelphia, PA 19124-1799