

CARDONE ProTech

Supporting Today's Professional Technician



1997 Chrysler 3.5L Water Pump — 3 or 6 Mounting Holes?

Application:

1997 Chrysler Concorde, Chrysler Intrepid (Canada), Chrysler LHS, Dodge Intrepid and Eagle Vision with 3.5L engine.

Problem:


Original water pump does not match replacement unit – the number of mounting holes is different.

Cause:


Mid-year design change by the OEM.

Solution:

CARDONE is now supplying two different housings. The part numbers are 58-541 and 58-564.



58-541 with 3 mounting holes



58-564 with 6 mounting holes

For other ProTech publications, visit www.cardone.com
CARDONE Industries, Inc. • 5501 Whitaker Ave. • Philadelphia, PA 19124-1799