

CARDONE ProTech

Supporting Today's Professional Technician



Distributor Replaced: Check Engine Light Still On

Application: Most OBDII equipped vehicles (1995 and newer).

Problem: Check engine light still on after distributor replacement.

Cause: Original trouble code was not cleared from the computer.

Solution: On some vehicles, permanent stored trouble codes must be manually cleared. After distributor replacement, if codes remain (check engine light still on), they must be erased using a suitable scan tool. Refer to your vehicle's service manual for proper procedures.



For other ProTech publications, visit www.cardone.com
CARDONE Industries, Inc. • 5501 Whitaker Ave. • Philadelphia, PA 19124-1799