

CARDONE ProTech

Supporting Today's Professional Technician



Chrysler CV ID Guide

Application:

Chrysler front wheel drive axles.

Problem:


CV driveaxle replacement units are different.

Cause:

Chrysler uses four different design joints.

Solution:

All four designs are interchangeable as long as the complete axle is installed.



Note: Replacement wheel joint for GKN design may have a flat surface here.

Note:

Chrysler CV axles MUST be handled with extreme caution! The inboard joint is spring loaded and may pop loose, causing a total malfunction and VOID THE WARRANTY.

For other ProTech publications, visit www.cardone.com
 CARDONE Industries, Inc. • 5501 Whitaker Ave. • Philadelphia, PA 19124-1799

FROST & SULLIVAN

Market Engineering Award Recipient

Product Quality Leadership

2002



Some things speak for themselves.

Frost & Sullivan is a leader in international strategic market consulting and training. They present Market Engineering Awards to companies that demonstrate diligence, perseverance and dedication in the global marketplace.

REMANUFACTURED CV DRIVE AXLES

CARDONE[®]

BRAKES • DRIVETRAIN • ELECTRONICS • MOTORS • PUMPS • STEERING

CARDONE Industries, Inc. 5501 Whitaker Ave., Philadelphia, PA 19124-1799 www.cardone.com 1-800-777-4304