


Chrysler CV ID Guide

Application: Chrysler front wheel drive axles.

Problem: CV driveaxle replacement units are different.

Cause: Chrysler uses four different design joints.

All four designs are interchangeable as long as the complete axle is installed.



Note:

Chrysler CV axles MUST be handled with extreme caution! The inboard joint is spring loaded and may pop loose, causing a total malfunction and VOID THE WARRANTY.

For other ProTech publications, visit www.cardone.com
CARDONE Industries, Inc. • 5501 Whitaker Ave. • Philadelphia, PA 19124-1799

MS8166 PT 60-0003

FROST & SULLIVAN

Market Engineering Award Recipient
Product Quality Leadership 2002



Some things speak for themselves.

Frost & Sullivan is a leader in international strategic market consulting and training. They present Market Engineering Awards to companies that demonstrate diligence, perseverance and dedication in the global marketplace.

REMANUFACTURED CV DRIVE AXLES CARDONE®

Brakes • Drivetrain • Electronics • Motors • Pumps • Steering

CARDONE Industries, Inc. 5501 Whitaker Ave., Philadelphia, PA 19124-1799 www.cardone.com 1-800-777-4304